

LOT LOCATION:  
CUSTOMER #: 129604  
UNIT# 14

169579

*Peterbilt of Utah*

INVOICE

1910 South 5500 West  
Salt Lake City, Utah 84104

BLUE ROCK LLC  
47 W FIRECLAY AVE APT 326  
MURRAY, UT 84107  
HOME:801-699-3149 CONT:801-699-3149  
BUS: CELL:

PAGE 1

P.O. Box 27634  
Salt Lake City, Utah 84127  
Phone (801) 486-8781

SERVICE ADVISOR: 2189 TJ Salazar

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN/ OUT		TAG
CREAM	14	KENWORTH W900		1XKWD49X9EJ412350			636032/636032		T14
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP13 DD			23:00 20DEC21		CASH	0.00	CASH	07JAN22	
R.O. OPENED		READY		OPTIONS: DLR:P250 ENG:79687791 TRN:S1037837					
20DEC21		07JAN22							

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	CONTACT # 801-699-3149						
	IF CONTACT # 801-699-3149						
	999 IP04						(N/C)
	*****						

B WHEN APPLYING BRAKES TRUCK SHAKES

ABS WHEN APPLYING BRAKES TRUCK SHAKES

847	C			1669.50	1669.50
1	R13-1014 BUSH		163.85	163.85	163.85
3	HWU05730 WASHER-ROUND SAE 5/16 GR8 ZN/YEL		0.19	0.17	0.51
1	CM10082209 HUB ASSY		510.66	450.41	450.41
1	450755-8CHR GASKET		1.88	1.71	1.71
1	10047LUC OIL-GEAR SYNTHETIC 75/90 QT (12)		16.12	14.67	14.67

MISC FRT ON HUB

CFT 82.00 82.00

636032 847 TEST DROVE, GOT WITH CUSTOMER AND CHECK FRONT END OUT.  
FOUND BUSHING GOING THROUGH CAB BROKEN. P AND A THEN REMOVE STEERING  
SHAFT AND LOWER DASH COVER. CHANGE IT OUT. DISASSEMBLE BOTH SIDE DRUMS  
AND BRAKES FOUND HUB ON PASS SIDE ALIGNMENT TABS WORN OFF CAUSING DRUM  
MISALIGNMENT P AND A NEW HUB GET IT REMOVE OLD ONE INSTALL NEW ONE TEST  
DRIVE ALL WENT WELL HAD FORMAN DRIVE HE WAS GOOD WITH IT CLEAN BAY

\*\*\*\*\*

C \*\*\*QUICK-LUBE SPECIAL\*\*\* CUSTOMER WANTS 15W40

QUICK \*\*\*QUICK-LUBE SPECIAL\*\*\*

2271	CQ			199.95	199.95
3	10047LUC OIL-GEAR SYNTHETIC 75/90 QT (12)		16.12	14.02	42.06
47	105816EXX M-DEL 1300S 15W40 BULK		4.43	3.29	154.63
1	P559000 FILTER-OIL		63.84	35.27	35.27
1	P555776 FILTER-FUEL SPIN ON		73.12	40.40	40.40
1	P550851 FILTER-FUEL/WATER SEPARATOR				
	CARTRIDGE		35.24	19.47	19.47

HAZ HAZARDOUS WASTE ENVIRONMENTAL FEE

999 CHAZ 25.00 25.00

636032 2271- PERFORM SERVICE TRAINING NEW TECH OIL GUN DOSE NOT

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRIPTION	TOTALS
		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		SALES TAX	
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

LOT LOCATION:  
CUSTOMER #: 129604  
UNIT# 14

169579

*Peterbilt of Utah*

INVOICE

1910 South 5500 West  
Salt Lake City, Utah 84104

BLUE ROCK LLC  
47 W FIRECLAY AVE APT 326  
MURRAY, UT 84107  
HOME:801-699-3149 CONT:801-699-3149  
BUS: CELL:

PAGE 2

P.O. Box 27634  
Salt Lake City, Utah 84127  
Phone (801) 486-8781

SERVICE ADVISOR: 2189 TJ Salazar

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN/ OUT		TAG
CREAM	14	KENWORTH W900		1XKWD49X9EJ412350			636032/636032		T14
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
30SEP13 DD			23:00 20DEC21		CASH	0.00	CASH	07JAN22	
R.O. OPENED		READY		OPTIONS: DLR:P250 ENG:79687791 TRN:S1037837					
20DEC21		07JAN22							

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
WORK ON N-4 HAD TO US N-3 OIL GUN FOUND WHEEL SEAL LEAKING ON FORWARD DRIVE AXLE LEFT SIDE TRANS OUT PUT SEAL LEAKING HOSE ON POWER STEERING RESERVOIR LEAKING BLINKER ON RIGHT SIDE FENDER NOT WORKING FORWARD DIFF LEVEL WAS LOW FILL WITH GEAR OIL GREASE IS COME OUT OF CAP ON LEFT KINGPIN							

\*\*\*\*\*

D INSTALL DRIVER SEAT (PART IS IN WILL CALL), REMOVE PASSENGER SEAT PER CUSTOMER REQUEST							
MISC MISC REPAIRS							
847 C						238.50	238.50
1 188409MW61 SEAT-LEGACY LO SUSP HB 4W AIR LUM							
BLACK					1312.83	957.63	957.63
1 FG9005 FITTING-PUSHCON BRS UNION					18.99	17.28	17.28
1 G38-1045-0004 FITTING-PLUG J2494 COMPOSITE					4.00	3.64	3.64
636032 847 CHANGE OUT DRIVER SEAT AND REMOVE PASS SIDE							

\*\*\*\*\*

E INSTALL CB RADIO (RADIO ON SEAT)							
ACC INSTALL CB RADIO (RADIO ON SEAT)							
847 C						79.50	79.50
1 29LTD RADIO-CB COBRA 29 VERSION CLASSIC					115.16	87.04	87.04
1 TSM4PS ANTENNA-PROSTICK CB, 4' WHITE 50PK							
BULK					7.07	6.43	6.43
636032 847 GET OK TO INSTALL NEW CB SO I DID AND INSTALL NEW ANTENNA							

\*\*\*\*\*

EST: 216.67 20DEC21 14:39 SA: 2189

CONTACT:  
\*\*\*\*\*

SHAKING WHEN BRAKING

PETERBILT "TRUCKCARE"  
(800)473-8372

24 HOUR EMERGENCY ROADSIDE SERVICE  
WWW.PETERBILT.COM

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRIPTION	TOTALS
		LABOR AMOUNT	2212.45
		PARTS AMOUNT	1995.00
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES	300.75
		TOTAL CHARGES	4508.20
		LESS INSURANCE	0.00
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	SALES TAX	342.63
		PLEASE PAY THIS AMOUNT	4850.83

CUSTOMER COPY