

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount	
D-D8N-8 (Dozer)	S26139	3/10/2015	8,151 Hours Meter reading: 8151 65-install right blade lift cylinder.	Kyle Bundy Routine Work	65	\$0.00	\$58.00	\$58.00	
	Totals for S26139						\$0.00	\$58.00	\$58.00
	S26169	2/18/2015	Meter reading: none listed Repair-Leaking blade lift cylinder Correction: 2/18/15 Arrived to the machine and removed the leaking blade cylinder, capped the lines on the machine side. The cylinder will be picked up by Mike and taken into SLC for repair. The serial number has been written on the cylinder. 2/20/15 Steam clean and disassemble cylinder. Inspect cylinder. Had to have cylinder housing hones, rod straightened and rechromed. 3/2/15 Assembled cylinder with new parts.	Komatsu Routine Work	MS	\$0.00	\$0.00	\$0.00	
	Totals for S26169						\$0.00	\$0.00	\$0.00
	S24220	11/8/2013	8,128 Hours check and replace one battery and repair positive cable.	Kyle Bundy Routine Work	30	\$0.00	\$72.50	\$72.50	
	Totals for S24220						\$0.00	\$72.50	\$72.50
	S24135	10/23/2013	replace hyd hose for tilt cyl.	Kyle Bundy Routine Work	65	\$0.00	\$58.00	\$58.00	
	Totals for S24135						\$0.00	\$58.00	\$58.00
	S23676	7/19/2013	8,000 Hours repair wiring for coolant flow sensor	Kyle Bundy Routine Work	30	\$0.00	\$72.50	\$72.50	
	Totals for S23676						\$0.00	\$72.50	\$72.50
Komatsu (N44333)	S24175	6/24/2013 6/24/2013		Routine Work	51	\$0.00	\$121.91	\$121.91	
	Totals for S24175						\$0.00	\$121.91	\$121.91
	S26269	6/13/2013	Meter reading: None indicated 6/13/13-6/24/13 Tighten customer's cutting edges Correction: Checked cutting edges, they were loose. Tighten cutting edges to spec, checked over machine to make sure everything working properly.	Komatsu Routine Work	50	\$9.91	\$112.00	\$121.91	
Totals for S26269						\$9.91	\$112.00	\$121.91	

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	S14817	10/19/2006	5,189 Hours	Kyle Bundy Routine Work	65	\$0.00	\$67.50	\$67.50
			REPLACE O RINGS ON FILTER & HOUSING IN SCOFIELD					
						Totals for S14817	\$0.00	\$67.50
	S14110	8/1/2006	4,943 Hours	Troy Bentley Routine Work	90	\$0.00	\$660.00	\$660.00
			replace rear idler					
						Totals for S14110	\$0.00	\$660.00
	S13749	6/20/2006		Troy Bentley Routine Work	90	\$0.00	\$288.00	\$288.00
			Clean Belly pions Steam Radiator					
						Totals for S13749	\$0.00	\$288.00
	S13799	6/15/2006		Troy Bentley Routine Work	90	\$0.00	\$180.00	\$180.00
			Replace broken idler bolts					
						Totals for S13799	\$0.00	\$180.00
	S14217	6/15/2006		Troy Bentley Routine Work	90	\$0.00	\$275.00	\$275.00
			replace broken idler bolts.					
						Totals for S14217	\$0.00	\$275.00
	S13641	5/23/2006		Troy Bentley Routine Work	02	\$0.00	\$36.00	\$36.00
			Repair grill					
						Totals for S13641	\$0.00	\$36.00
	S12993	1/13/2006	4,432 Hours	Anthony Dixon PM Services	PM	\$0.00	\$14.25	\$14.25
			A-PM					
						Totals for S12993	\$0.00	\$14.25
	S13026	1/7/2006		Terry Stephenson Routine Work	MS	\$0.00	\$330.00	\$330.00
			Replace vibration dampener on engine, repair alternator bracket					
						Totals for S13026	\$0.00	\$330.00
	S12035	6/16/2005	4,175 Hours	Anthony Dixon PM Services	PM	\$0.00	\$28.50	\$28.50
			A-PM					
						Totals for S12035	\$0.00	\$28.50
	S11848	5/19/2005	4,078 Hours	Kyle Bundy Routine Work	40	\$0.00	\$108.00	\$108.00
			Replace starter					
						Totals for S11848	\$0.00	\$108.00
	S11499	3/11/2005		Loury Hansen Routine Work	MS	\$0.00	\$72.00	\$72.00
			Repair right idler					
						Totals for S11499	\$0.00	\$72.00
	S11370	2/14/2005	3,920 Hours	Anthony Dixon PM Services	PM	\$0.00	\$71.25	\$71.25
			A-PM, B-PM, C-PM					
						Totals for S11370	\$0.00	\$71.25
	S10976	11/5/2004	3,850 Hours	Anthony Dixon PM Services	PM	\$0.00	\$28.50	\$28.50
			A-PM. B-PM					
						Totals for S10976	\$0.00	\$28.50

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	S08087	2/13/2003	3,123 Hours	Troy Bentley				
				Routine Work	30	\$0.00	\$72.00	\$72.00
			Repair lights and install new wipers.	Routine Work	40	\$0.00	\$165.00	\$165.00
			Repair ether aid.					
				Totals for S08087		\$0.00	\$237.00	\$237.00
	S08025	2/3/2003	3,112 Hours	Anthony Dixon				
				PM Services	PM	\$0.00	\$57.00	\$57.00
			A-PM					
				Totals for S08025		\$0.00	\$57.00	\$57.00
	S07893	1/22/2003		Troy Bentley				
				Routine Work	02	\$0.00	\$18.00	\$18.00
			reinstalled belly pan					
				Totals for S07893		\$0.00	\$18.00	\$18.00
	S07896	1/22/2003		Terry Stephenson				
				Breakdown	42	\$0.00	\$110.00	\$110.00
			finished radiator instalation	Breakdown	44	\$0.00	\$55.00	\$55.00
			worked on fuel injection pump					
				Totals for S07896		\$0.00	\$165.00	\$165.00
	S07860	1/21/2003		Loury Hansen				
				Breakdown	42	\$0.00	\$306.00	\$306.00
			repaired radiator					
				Totals for S07860		\$0.00	\$306.00	\$306.00
	S07862	1/21/2003		Terry Stephenson				
				Breakdown	42	\$0.00	\$412.50	\$412.50
			repaired radiator					
				Totals for S07862		\$0.00	\$412.50	\$412.50
	S07866	1/20/2003		Terry Stephenson				
				Breakdown	42	\$0.00	\$330.00	\$330.00
			pulled radiator for repairs					
				Totals for S07866		\$0.00	\$330.00	\$330.00
	S07815	1/15/2003		Terry Stephenson				
				Breakdown	42	\$0.00	\$55.00	\$55.00
			worked on radiator					
				Totals for S07815		\$0.00	\$55.00	\$55.00
	S07788	1/11/2003		Terry Stephenson				
				Breakdown	40	\$0.00	\$330.00	\$330.00
			repaired engine miss					
				Totals for S07788		\$0.00	\$330.00	\$330.00
	S07787	1/10/2003		Terry Stephenson				
				Breakdown	40	\$0.00	\$110.00	\$110.00
			worked on engine problem					
				Totals for S07787		\$0.00	\$110.00	\$110.00
	S07818	12/27/2002	3,048 Hours	Terry Stephenson				
				Routine Work	02	\$0.00	\$55.00	\$55.00
			pulled belly pan and checked					
				Totals for S07818		\$0.00	\$55.00	\$55.00
	SYS07225	11/15/2002		Terry Stephenson				
				Breakdown	40	\$0.00	\$0.00	\$0.00
			worked on engine miss					
				Totals for SYS07225		\$0.00	\$0.00	\$0.00

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	SYS06796	10/17/2002		Terry Stephenson Breakdown	42	\$0.00	\$0.00	\$0.00
			radiator repair					
				Totals for SYS06796		\$0.00	\$0.00	\$0.00
	SYS06770	10/16/2002		Troy Bentley Breakdown	42	\$0.00	\$0.00	\$0.00
			removed radiator for repairs					
				Breakdown	62	\$0.00	\$0.00	\$0.00
			repaired ripper control linkage and cleaned belly pans					
				Totals for SYS06770		\$0.00	\$0.00	\$0.00
	SYS06771	10/16/2002		Terry Stephenson Breakdown	40	\$0.00	\$0.00	\$0.00
			worked on engine miss					
				Breakdown	42	\$0.00	\$0.00	\$0.00
			worked on radiator removal					
				Totals for SYS06771		\$0.00	\$0.00	\$0.00
	SYS06750	10/15/2002		Troy Bentley Breakdown	40	\$0.00	\$0.00	\$0.00
			checked engine miss					
				Breakdown	42	\$0.00	\$0.00	\$0.00
			repaired radiator					
				Totals for SYS06750		\$0.00	\$0.00	\$0.00
	SYS06762	10/15/2002		Terry Stephenson Breakdown	42	\$0.00	\$0.00	\$0.00
			worked on radiator					
				Totals for SYS06762		\$0.00	\$0.00	\$0.00
	SYS06703	10/9/2002		Troy Bentley Breakdown	62	\$0.00	\$0.00	\$0.00
			dozer bolts loose					
				Totals for SYS06703		\$0.00	\$0.00	\$0.00
	SYS06684	10/8/2002		Terry Stephenson Breakdown	62	\$0.00	\$0.00	\$0.00
			repair dozer and ripper tooth					
				Totals for SYS06684		\$0.00	\$0.00	\$0.00
	SYS06655	10/4/2002		Terry Stephenson Breakdown	42	\$0.00	\$0.00	\$0.00
			worked on radiator leak					
				Totals for SYS06655		\$0.00	\$0.00	\$0.00
	SYS06460	9/26/2002	2,916 Hours	Bill Huber PM Services	PM	\$0.00	\$0.00	\$0.00
			B-PM					
				Totals for SYS06460		\$0.00	\$0.00	\$0.00
	SYS06315	9/17/2002		Troy Bentley Breakdown	50	\$0.00	\$0.00	\$0.00
			replaced grease zert					
				Totals for SYS06315		\$0.00	\$0.00	\$0.00
	SYS06280	9/16/2002		Troy Bentley Breakdown	65	\$0.00	\$0.00	\$0.00
			repaired lift cylinder					
				Totals for SYS06280		\$0.00	\$0.00	\$0.00
	SYS06283	9/16/2002		Terry Stephenson Breakdown	65	\$0.00	\$0.00	\$0.00
			repaired left hand dozer cylinder and cracks in covers					
				Totals for SYS06283		\$0.00	\$0.00	\$0.00

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	SYS04051	5/21/2002		Terry Stephenson				
			installed turbocharger	Breakdown	40	\$0.00	\$0.00	\$0.00
				Totals for SYS04051		\$0.00	\$0.00	\$0.00
	SYS04058	5/21/2002		Troy Bentley				
			tightened tracks	Breakdown	20	\$0.00	\$0.00	\$0.00
			installed turbo and adjusted AC belts	Breakdown	40	\$0.00	\$0.00	\$0.00
				Totals for SYS04058		\$0.00	\$0.00	\$0.00
	SYS04035	5/20/2002		Troy Bentley				
			installed seal on H-bar	Breakdown	65	\$0.00	\$0.00	\$0.00
				Totals for SYS04035		\$0.00	\$0.00	\$0.00
	SYS04048	5/20/2002		Terry Stephenson				
			replaced turbocharger	Breakdown	40	\$0.00	\$0.00	\$0.00
				Totals for SYS04048		\$0.00	\$0.00	\$0.00
	SYS03762	5/14/2002	2,576 Hours	Anthony Dixon				
			A-PM	PM Services	PM	\$0.00	\$0.00	\$0.00
				Totals for SYS03762		\$0.00	\$0.00	\$0.00
	SYS03527	5/8/2002		Troy Bentley				
			shimed up trunions	Breakdown	50	\$0.00	\$100.00	\$100.00
				Totals for SYS03527		\$0.00	\$100.00	\$100.00
	SYS03502	5/7/2002		Troy Bentley				
			installed tilt cylinder and welded in trunion balls	Breakdown	50	\$0.00	\$400.00	\$400.00
				Totals for SYS03502		\$0.00	\$400.00	\$400.00
	SYS02673	4/12/2002		Terry Stephenson				
			reassembled dozer	Routine Work	50	\$0.00	\$0.00	\$0.00
				Totals for SYS02673		\$0.00	\$0.00	\$0.00
	SYS02733	4/12/2002		Troy Bentley				
			reassembled dozer	Breakdown	50	\$0.00	\$0.00	\$0.00
				Totals for SYS02733		\$0.00	\$0.00	\$0.00
	SYS02640	4/11/2002		Terry Stephenson				
			worked on pivot shafts	Breakdown	16	\$0.00	\$0.00	\$0.00
				Totals for SYS02640		\$0.00	\$0.00	\$0.00
	SYS02726	4/11/2002	2,479 Hours	Wheeler Machinery				
			recharged ac (employee # 912)	Routine Work	01	\$0.00	\$0.00	\$0.00
				Totals for SYS02726		\$0.00	\$0.00	\$0.00
	SYS02043	3/8/2002	2,363 Hours	Anthony Dixon				
			C-PM	PM Services	PM	\$0.00	\$0.00	\$0.00
				Totals for SYS02043		\$0.00	\$0.00	\$0.00

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount	
	SYS01328	11/13/2001	2,101 Hours	Anthony Dixon PM Services	PM	\$0.00	\$0.00	\$0.00	
			A-PM						
				Totals for SYS01328			\$0.00	\$0.00	\$0.00
	SYS01036	9/18/2001	1,873 Hours	Anthony Dixon PM Services	PM	\$0.00	\$0.00	\$0.00	
			A-PM						
				Totals for SYS01036			\$0.00	\$0.00	\$0.00
	SYS00772	8/2/2001	1,630 Hours	Anthony Dixon PM Services	PM	\$0.00	\$0.00	\$0.00	
			A-PM						
				Totals for SYS00772			\$0.00	\$0.00	\$0.00
	SYS01493	7/10/2001		Wheeler Machinery Routine Work	MS	\$0.00	\$0.00	\$0.00	
			Install new rollers, bogie pins and wear guides.						
				Totals for SYS01493			\$0.00	\$0.00	\$0.00
	SYS00377	5/22/2001	1,382 Hours	Anthony Dixon PM Services	PM	\$0.00	\$0.00	\$0.00	
			A-PM						
				Totals for SYS00377			\$0.00	\$0.00	\$0.00
	SYS00251	4/11/2001	1,169 Hours	PM Services	PM	\$0.00	\$0.00	\$0.00	
			A-PM						
				Totals for SYS00251			\$0.00	\$0.00	\$0.00
	SYS00175	3/31/2001	1,124 Hours	Bruce Thomas Routine Work	41	\$0.00	\$0.00	\$0.00	
			New inner and outer air filters.						
				Totals for SYS00175			\$0.00	\$0.00	\$0.00
	SYS01492	8/24/2000		Wheeler Machinery Routine Work	40	\$0.00	\$0.00	\$0.00	
			Remove engine and send to wheeler to repair. Inframe, out of frame and overhead. Reinstall engine. Replace pins and bushings on rear bores of hard nose mountings.						
				Totals for SYS01492			\$0.00	\$0.00	\$0.00
	SYS01494	5/8/2000		Wheeler Machinery Routine Work	MS	\$0.00	\$0.00	\$0.00	
			Exchange torque converter and replace housing with a used one. Replace right dozer cylinder rod with O.R. rod. Replace all seals and packing and replace hyd. hoses. Install new sprocket segments. Install new front horns. Install new hyd. oil cooler core. Replace bearings and seals in fan drive and idler pulley. Fix seat. Install used dozer adjusting arm. Replace muffler & precleaner. Repair radiator cores, install new seals on top and bottom tanks, replace all rubber hoses and coolant tubes. Install new a/c condenser core. Exchange steering motor and hyd. pump. Install new relief valve.						
				Totals for SYS01494			\$0.00	\$0.00	\$0.00
	SYS01526	4/5/2000		Wheeler Machinery Routine Work	01	\$0.00	\$0.00	\$0.00	
			Change A/C to R134.						
				Totals for SYS01526			\$0.00	\$0.00	\$0.00
				Totals			\$9.91	\$15,420.66	\$15,430.57
				Grand Totals			\$9.91	\$15,420.66	\$15,430.57