



COLOR COUNTRY DIESEL INC.
2615 FREEWAY DRIVE
CEDAR CITY, UT. 84721
PH: (435) 586-3205

INVOICE W 202619

Date Closed 03/16/23

Date Open 03/15/23

Page: 1 of 2

Sold To : 668-0500 435

Ship To :

SEVY LAND & LIVESTOCK
PO BOX 2593

CEDAR CITY UT 84721 USA

Written By	Terms	Time	Customer Po #	OPEN	Phone	Ship Via
Sadie	CASH	13:22:23				

Unit #	Plate #	Year	Make	Model	Mileage/Hrs	VIN	Engine
7	7	2014	KENWORTH	W900	511369/0.0	1XKW049X8FJ425740	CUMMINS

Qty	Description	Price	Amount
8.760	REMOVED AND REPLACED WIPERS. HAD TO REPLACE PIGGYBACK ON THE RIGHT, FRONT DRIVE AXLE. JACKED UP LEFT, FRONT DRIVE AXLE AND REMOVED TIRES, DRUM, AXLE AND HUB. CLEARED HUB AND BEARINGS. REPLACED HUB SEAL. PUT TOGETHER AND ADJUSTED BRAKES TO SPEC. PARKED ON OTHER SIDE OF ELECTRICAL BUILDING.		1095.00
2.000	ALLN82-W18 18" WINTER WIPER BLADES	12.70	25.40
1.000	MIDKN36470 CLEVIS ASSY.	2.50	2.50
1.000	VALPYROIL WASHER FLUID CNCNTR	3.40	3.40
3.000	TEC21269 pre-made brake hose	14.33	42.98
1.000	ANC30PB PIGGY BACK, TYPE 30	75.70	75.70
1.000	LAW5314 3/8 45 STREET ELBOW	6.93	6.93
1.000	FLGLF14000NN OIL FILTER	57.99	57.99
1.000	FLGFF5825NN FUEL FILTER	70.57	70.57
1.000	CUMFS36401 PAC,FS	51.76	51.76
11.00	XXXBULK OIL MOTOR OIL, 15W-40	18.92	208.07
2.000	XXEP2 GREASE, HIGH TEMP	5.25	10.50
1.000	STE330-3111 AXLE GASKET	3.71	3.71
1.000	STE309-0973 SEAL, WHEEL	88.51	88.51
2.000	PACL71-1004 hood spring brown	300.59	601.17

I authorize the above repair work, including sublet work, to be done along with necessary materials. COLOR COUNTRY DIESEL INC employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. COLOR COUNTRY DIESEL INC will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.

Parts..... 1249.19
Labor..... 1095.00

Freight..... 22.00



INVOICE W 202619

Date Closed 03/16/23

Date Open 03/15/23

Page: 2 of 2

Sold To : 068-0500	435
--------------------	-----

Ship To :

SEVY LAND & LIVESTOCK
PO BOX 2593

CEDAR CITY UT 84721 USA

Written By Sadie		Terms CASH		Time 13:22:24		Customer Po #		OPEN		Phone		Ship Via	
Unit # 7		Plate # 7		Year 2014		Make KENWORTH		Model W900		Mileage/Hrs 511369/0 0		VIN 1XXW049X8FJ425740	
Engine CUMMINS													

Qty	Description	Price	Amount
1.000	FRTINCOMING INCOMING FREIGHT CHARGES	22.00	22.00

Although the above repair work, including but not limited to, is to be done using only necessary materials, COLOR COUNTRY DIESEL, INC. employees may operate above listed vehicle for purposes of testing, inspection or delivery at his own risk. An express Merchant's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. COLOR COUNTRY DIESEL, INC. will not be held responsible for loss or damage to above listed vehicle, to extent set in above listed vehicle's acknowledgement receipt of a copy hereof.

Parts.....	1249.19
Labor.....	1095.00

Freight.....	22.00
--------------	-------

Thank you for your business and we look forward to serving you again.

Paid by CHK# 1120

TOTAL PAID	2366.19
CHK# 1120	2366.19
CHANGE	



COLOR COUNTRY DIESEL INC.
2615 FREEWAY DRIVE
CEDAR CITY, UT. 84721
PH: (435) 586-3205

INVOICE W 203654
Date / /
Date Open 08/09/2023

Page: 1 of 2

Sold To : 866-0500 435

Ship To :

SEVY LAND & LIVESTOCK
PO BOX 2593

CEDAR CITY UT 84721 USA

Written By Sadie	Terms CASH	Time 15:39:34	Customer Po #	OPEN	Phone	Ship Via
---------------------	---------------	------------------	---------------	------	-------	----------

Unit # 7	Plate # 7	Year 2014	Make KENWORTH	Model W900	Mileage/Hrs 0/0.0	VIN 1XKW049X8FJ425740	Engine CUMMINS
-------------	--------------	--------------	------------------	---------------	----------------------	--------------------------	-------------------

Qty	Description	Price	Amount
44.69	CHECKED TO SEE WHY WATER WAS IN THE OIL. REMOVED VALVE COVER AND FOUND THAT THE OIL WAS MILKY. I REMOVED OIL PAN AND PRESSURED UP COOLANT SYSTEM. FOUND COOLANT LEAKING OUT OF #3 AND #4 LINERS. REMOVED RADIATOR AND HEAD. CHECKED HEAD AND GASKETS AND FOUND HEAD WAS CRACKED. MEASURED LINERS. CUSTOMER WANTED TO IN FRAME MOTOR. REMOVED LINERS AND PISTONS AND CLEANED UP ENGINE BLOCK. INSTALLED NEW LINERS, MEASURED COUNTER BORES AND INSTALLED NEW PISTONS. REPLACED RODS AND MAIN BEARINGS. PUT OIL PAN BACK ON. INSTALLED NEW HEAD AND HOOKED EVERYTHING UP. RAN OVER HEAD AND INSTALLED RADIATOR. FILLED FLUIDS AND STARTED TRUCK. TEST DROVE AND FOUND THAT THE AC COMPRESSOR FUSE KEPT BLOWING. CHECKED ELECTRICAL FOUND AC CLUTCH WAS BAD. REPLACED AC COMPRESSOR AND REPLACED DRIER. CHARGED AC AND CHECKED COMPRESSOR. WASHED AND PAINTED ENGINE. ***NO CHARGE FOR FREON***		5586.25
1.000	5693737 OVERHAUL	8000.01	8000.01
1.000	5658301 CYLINDER HEAD	6750.01	6750.01
2.000	LAW90782 SILCONE HOSE CLAMP	2.56	5.12
12.00	PUR80-075-25 3/4 HEATER HOSE	4.58	54.96
12.00	CUM3678806 SEAL, O RING	3.42	41.03

I authorize the above repair work, including related work, to be done along with necessary materials. COLOR COUNTRY DIESEL INC. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Merchant's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereon. COLOR COUNTRY DIESEL INC. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.

Parts..... 16347.94
Labor..... 5586.25

Thank you for your business and we look forward to serving you again.

Freight..... 91.00

Service..... 175.00

Paid by _____

TOTAL Continued



COLOR COUNTRY DIESEL INC.
2615 FREEWAY DRIVE
CEDAR CITY, UT, 84721
PH: (435) 586-3205

INVOICE W 203654
Date / /
Date Open 08/09/2023

Page: 2 of 2

Sold To : 668-0500 435

Ship To :

SEVY LAND & LIVESTOCK
PO BOX 2593

CEDAR CITY UT 84721 USA

Written By Sadie		Terms CASH		Time 15:39:34		Customer Po #		OPEN		Phone		Ship Via			
Unit # 7		Plate # 7		Year 2014		Make KENWORTH		Model W900		Mileage/Hrs 0/0.0		VIN 1XKW049X8FJ425740		Engine CUMMINS	

Qty	Description	Price	Amount
1.000	FRTINCOMING INCOMING FREIGHT CHARGES	91.00	91.00
1.000	PACF04-6006 ELBOW HOSE	130.13	130.13
2.000	BRECT300L CLAMP, CONSTANT TORQ	12.47	24.93
2.000	NAP500009 NAPA GOLD AIR FILTER	164.40	328.80
12.50	XXBULK OIL MOTOR OIL, 15W-40	23.76	296.99
1.000	QTRPTAC5362 12V SANDEN	281.61	281.61
13.00	FLGFINAL CHARGE 50/50 EXTND LIFE ANTIFREEZE	16.37	212.81
25.00	LAW5676 TIE, 15X3/16 NYLON	0.62	15.50
1.000	SVCSHOPSUP SHOP SUPPLIES	175.00	175.00
4.000	DE1653 CUMMINS RED HIGH TEMP. PAINT	16.50	65.99
1.000	PACF37-1016 reciever drier	140.05	140.05

I authorize the above repair work, including labor work, to be done along with necessary materials. COLOR COUNTRY DIESEL, INC. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Merchant's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. COLOR COUNTRY DIESEL, INC. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle. I acknowledge receipt of a copy hereof.

Parts..... 16347.94
Labor..... 5586.25

Freight..... 91.00

Service..... 175.00

Paid by _____

TOTAL 22200.19



Color Country Diesel Inc.
2615 FREEWAY DRIVE
CEDAR CITY, UT. 84721
PH: (435) 586-3205

INVOICE W 204670

Date Closed 01/17/24

Date Open 01/17/24

Page: 1 of 1

Sold To : 668-0500 435

Ship To :

SEVY LAND & LIVESTOCK
PO BOX 2593

CEDAR CITY UT 84721 USA

Written By	Terms	Time	Customer Po #	OPEN	Phone	Ship Via
JORDAN	CASH	16:15:14				

Unit #	Plate #	Year	Make	Model	Mileage/Hrs	VIN	Engine
7	7	2014	KENWORTH	W900	0/0.0	1XKW049XBFJ425740	CUMMINS

Qty	Description	Price	Amount
14.00	TRUCK CAME IN FOR AN OIL LEAK, FOUND MULTIPLE. WE REPLACED THE FRONT CRANK SEAL, CRANKCASE BREATHER OIL DRAIN HOSE, RESEALED THE GEAR FUEL PUMP, RESEALED THE POWER STEERING PUMP SUCTION FITTING AND HOSE, REPLACED THE WEATHER STRIPPING ON BOTH SLEEPER DOORS, STEAMED OFF THE ENGINE, RAN AND TESTED FOR OIL LEAKS, GOOD TO GO		2100.00
2.000	PACT42-1002-2S30 compartment door seal	277.51	555.02
2.000	PACT42-1019 sleeper door seal	121.94	243.88
1.000	CUM3688012 TUBE LUB OIL DRAIN	50.41	50.41
1.000	CUM4903514 SEAL O RING	6.51	6.51
1.000	CUM3685173 SEAL OIL	78.70	78.70
2.000	LAW88710 SILICONE HOSE CLAMP	2.74	5.49
1.000	KENQ347367 DIP STICK	24.91	24.91
4.000	DEXATF FLUID, AUTO TRANS	1.95	7.90
1.000	DISCOUNT10 10% DISCOUNT	-307.28	-307.28

I authorize the above repair work, including sublet work, to be done along with necessary materials. COLOR COUNTRY DIESEL, INC. employees may tow/leave above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Merchant's Lien is acknowledged on above listed vehicle to secure the amount of repair charges. COLOR COUNTRY DIESEL, INC. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle. I acknowledge receipt of a copy hereof.

Parts..... 665.54
Labor..... 2100.00

Thank you for your business and we look forward to serving you again.

Paid by CHKE 1145

TOTAL 2765.54
PAID
CHKE 1145 2765.54
CHANGE



COLOR COUNTRY DIESEL INC.
2615 FREEWAY DRIVE
CEDAR CITY, UT. 84721
PH: (435) 586-3205

INVOICE W 204941

Date / /

Date Open 02/28/2024

Page: 1 of 2

Sold To : 668-0500 435

Ship To :

SEVY LAND & LIVESTOCK
PO BOX 2593

CEDAR CITY UT 84721 USA

Written By Sadie	Terms CASH	Time 13:10:30	Customer Po #	OPEN	Phone	Ship Via
---------------------	---------------	------------------	---------------	------	-------	----------

Unit # 7	Plate # 7	Year 2014	Make KENWORTH	Model W900	Mileage/Hrs 523637/0.0	VIN 1XKW049X8FJ425740	Engine CUMMINS
-------------	--------------	--------------	------------------	---------------	---------------------------	--------------------------	-------------------

Qty	Description	Price	Amount
17.60	FULL SERVICE ON SEMI TRUCK CHANGE OIL, OIL FILTER'S, AND FUEL FILTER'S. CHECK THE AIR FILTERS, BRAKES, TIRES, LIGHTS, AXLE OIL, AND DRIVE LINE/J JOINTS. TOP OFF POWER STEERING FLUID, WASHER FLUID, & COOLANT. GREASE ALL FITTINGS, ZERKS AND THE 5th WHEEL PLATE. HOOKED UP INSITE AND RESET GEAR RATIO FROM 3.70 TO 3.36. SET CRUISE IDLE. REMOVED BOTH REAR ENDS, CLEANED UP, AND INSPECTED FOR METAL. INSTALLED NEW REAR ENDS- DIFFERENT GEAR RATIO. REMOVED FRONT U-BOLTS. ADDED ONE LEAF ON BOTH FRONT SPRINGS. REMOVED BLOCKS. HAD TO REPLACE U-BOLTS. STEAMED OFF AND TEST DROVE.		2670.00
1.000	FRTINCOMING INCOMING FREIGHT CHARGES	240.00	240.00
2.000	LAW80931 1/2-13 TOP LOCK NUT	0.62	1.25
22.60	XXX75W90 SYNTHETIC GEAR OIL*BULK* PER QUART	9.38	210.94
1.000	SVCINSITE CUMMINS COMPUTER HOOK UP FEE	55.00	55.00
4.000	STE330-3105 AXLE GASKET	2.85	11.39
1.000	VALPYROIL WASHER FLUID CNCNTRT	3.40	3.40

I authorize the above repair work, including sublet work, to be done along with necessary materials. COLOR COUNTRY DIESEL, INC. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. COLOR COUNTRY DIESEL, INC. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle / acknowledge receipt of a copy hereof.

Parts..... 6347.72
Labor..... 2670.00

Freight..... 240.00

Service..... 120.00

Thank you for your business and we look forward to serving you again.

Paid by _____

TOTAL Continued



COLOR COUNTRY DIESEL INC.
2615 FREEWAY DRIVE
CEDAR CITY, UT. 84721
PH: (435) 586-3205

INVOICE W 204941
Date / /
Date Open 02/28/2024

Page: 2 of 2

Sold To : 668-0500 435

Ship To :

SEVY LAND & LIVESTOCK
PO BOX 2593

CEDAR CITY UT 84721 USA

Written By Sadie	Terms CASH	Time 13.10.30	Customer Po #	OPEN	Phone	Ship Via
Unit # 7	Plate # 7	Year 2014	Make KENWORTH	Model W900	Mileage/Hrs 523637/0.0	VIN 1XKW049X8FJ425740
			Engine CUMMINS			

Qty	Description	Price	Amount
11.00	XXXDELO 400-15W-40 BU OIL, MOTOR BULK OIL NOT GALLON JUGS	21.16	232.80
2.000	XXEP2 GREASE, HIGH TEMP	6.11	12.22
1.000	FLGFF5825NN FUEL FILTER	74.87	74.87
1.000	FLGLF14000NN OIL FILTER	57.82	57.82
1.000	CUMFS36401 PAC.FS	37.14	37.14
1.000	REVEDS404336CF DS404 3.36 FRONT DRIVE AXLE SN#HN08475702	3373.50	3373.50
1.000	REVERSA404336CF RS404 3.36 REAR DRIVE AXLE SN#HN08416792	2242.50	2242.50
2.000	AAACB1212 1/2X12 CENTER BOLT	3.03	6.06
2.000	LEL1/2X5CB BOLT, GRADE 8	3.46	6.92
4.000	FLEOTRS81220 u-bolt, washer and nut	19.23	76.91
1.000	SVCFEDANN FEDERAL ANNUAL INSPECTION	65.00	65.00

I authorize the above repair work, including sublet work, to be done along with necessary materials. COLOR COUNTRY DIESEL, INC. employees may complete above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. COLOR COUNTRY DIESEL, INC. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle. I acknowledge receipt of a copy hereof.

Parts..... 6347.72
Labor..... 2670.00

Thank you for your business and we look forward to serving you again.

Freight..... 240.00

Service..... 120.00

Paid by _____

TOTAL 9377.72



COLOR COUNTRY DIESEL INC.
2615 FREEWAY DRIVE
CEDAR CITY, UT, 84721
PH: (435) 586-3205

INVOICE S 191673
Date / /
Date Open 02/02/2024

Page: 1 of 1

Sold To : 668-0500 435

Ship To :

SEVY LAND & LIVESTOCK
PO BOX 2593

CEDAR CITY UT 84721 USA

Written By Parts1		Terms CASH		Time 14:59:05		Customer Po #		OPEN		Phone		Ship Via			
Unit # 7		Plate # 7		Year 2014		Make KENWORTH		Model W900		Mileage/Hrs 0/0.0		VIN 1XKWD49X8FJ425740		Engine CUMMINS	

Qty	Description	Price	Amount
1.000	CUM3689485 PULLEY, IDLER	127.08	127.08
1.000	NAP38567 belt tensioner. 3651282	192.82	192.82
1.000	NAP38610 belt tensioner 3690067	195.16	195.16

I authorize the above repair work, including sublet work, to be done along with necessary materials. COLOR COUNTRY DIESEL, INC. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. COLOR COUNTRY DIESEL, INC. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.

Parts..... 515.06

Thank you for your business and we look forward to serving you again.

Paid by _____

TOTAL 515.06