

GENERAL APPEARANCE

Cor	nditio	on:	N=New		VG	=Very	Good G=Good F=Fair P=Poor NA=Not Ap	plicable	
	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Radiator Grill & Shroud									
Eng. Enclose Hood / Stack									
Fuel Tank									
Crankcase Guard / Battery Box									
Draw Bar									
Front Frame									
Rear Frame									
Bumper									

Counterweight				
Pre-Cleaner Bowl				
Cab or Canopy				
Steps / Ladder		H step bent a little.		
Grab Irons				
Paint				
Sheet Metal				
	Condition	Remarks	Parts	Labor
S.O.S. Taken	Yes No NA			
Cleaning Required	Yes No NA			
Notes				

SAFETY ITEMS

• ~

		Condition				Rema	rks		Parts	Labor
Safety Decals In Place	Yes 🖲	No								
Safety Decals Legible	Yes 🖲	No								
Rotating Beacon	Yes	No 🖲								
Signal Lights	Yes 🖲	No								
ROPS	Yes 🖲	No								
Warning Lights	Yes	No	NA							
Con	dition: I	N=New V	G=Very	Good C	G=Good	F =Fair	P =Poor	NA=Not A	pplicable	
	N VG	GF	P NA			Remark	(S		Parts	Labor
Horn										
Notes										

GAUGES, OPERATOR STATION, CONSOLE

Con	ditic	on:	N=N	ew	VG	=Ver	Good G=Good F=Fair P=Poor NA=Not Applicable			
	Ν	VG	G	F	Ρ	NA	Remarks	Parts	Labor	
Dash Console										
Gauges										
Switches										
Windshield Wipers							Needs windshield wiper blades.			
Heater										
Interior Lights										
Seat Cushion / Arm Rest										
Floor Boards										
EMS Panel / Warnings										
I	I	I	1	I	I	1	I	I		

Door Latches											
Glass/Mirrors				H mirror cracked.							
Air Conditioner				ooling.							
		Condition		Remarks	Parts	Labor					
Current Parts Manual	Yes	No ●									
Current Safety Manual	Yes •	No									
Current O&MM	Yes	No	NA								
Seat Belt	Yes 🖲	No	NA								
Back Up Alarm	Yes 🖲	No	NA								
ROPS Certification Plate	Yes	No									
Notes											
		Remarks Parts Labor									
Fuel Level											

ENGINE

		Condition		Remarks	Parts	Labor						
Oil Leaks	Yes	No ●										
Blow By	Yes	No	NA									
Knocking	Yes	No ●	NA									
Compression in Radiator	Yes	No ●	NA									
Water in Oil	Yes	No 🖲										
Fluid Levels OK?	Yes	No	NA									
EPA Decal	Yes •	No	NA									
				Remarks	Parts	Labor						
Anti-Freeze Color			Red									
Oil Pressure (H/L/N)												
Smoke (B/D/L/W)		Light - Black										

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Operating Condition							Active service code #6 injector not responding.		
Turbocharger / Blower									
Fuel Injection System									
Governor									
Engine Supports									
Air Cleaners									
Exhaust / Muffler									
Oil Filter Condition									

(CUT)	
Belts / Pulleys	
Notes	

COOLING SYSTEM

	Condi	ndition: N=New				VG	=Very	y Good	G=Good	F=Fair	P=Poor	NA=Not Ap	plicable	
	1	Ν	VG	G	F	Ρ	NA			Remark	s		Parts	Labor
Radiator														
Coolers														
Hoses														
Water Pump														
Fan														
Fan Drive														
Notes														
		Condition								Rema	rks		Parts	Labor
Leaks	۱	/es		No		N]						

ELECTRICAL, STARTING AND CHARGING SYSTEM

Con	Condition:			lew	VG=Very G		Good	G =Good	F =Fair	P =Poor	NA=Not Ap	plicable	
	N	VG	G	F	Р	NA			Remark	s		Parts	Labor
Batteries / Cables													
Starter													
Alternator													
Wiring													
Pre-Heater													
Lighting													
Notes													
			Со	nditic	n				Rema	rks		Parts	Labor
Ether Aid	Yes	s 🗌	No	• 🗌	N		Start	s good					
Block Heater	Yes	s 🗌	N	• 🗌	N								

TRANSMISSION

	Condition:		on:	N=New		VG=Very Good		G =Good	F =Fair	P =Poor	NA=Not Ap	plicable		
		Ν	VG	G	F	Р	NA			Remarl	ks		Parts	Labor
Transmission - Type														
Case														
Controls														
Seals														

Torque Converter			
Universal Joints			
Lines / Fittings	Transmission return hose at clamp wet.		
Transmission - Reverse Shifts			
Pump			
Oil Filter Condition (CUT)			
Operating Condition			
Transmission - Forward Shifts			
Cooler			
	Condition Remarks	Parts	Labor
Transmission - Noisy	Yes No NA		
Leaks	Yes No NA		
Notes			
	Remarks	Parts	Labor
Transmission Type			

STEERING

Cor	ditior	า:	N=N	ew	VG	=Very	/ Good G=Good F=Fair P=Poor NA=Not Ap	plicable	
	N	VG	G	F	Ρ	NA	Remarks	Parts	Labor
Front Axle									
Steering Linkage									
Steering Gear Box									
Tie Rods / Rod Ends									
Articulate P & B									
Steering Valves / Pumps									
Steering Cylinder									
Oil Lines							Steering hoses not clamped down properly.		
King Pins									
Wheel Lean Cylinder									
Supplemental Steer									
Notes									

BRAKE

. .

Condition:	N=New	VG=Verv Good	G=Good	F =Fair	P=Poor	NA=Not Applicable
contaition.			0 -0000	i –i ali	I -1 001	INA -NOLAPPIICADIC

	Ν	VG	G	F	Ρ	NA	Remarks	Parts	Labor
Type (Pedal, Lever)							Pedal		

Type (Wet, Dry)		/et		
Control Valve				
Lines				
Master Cylinder				
Compressor				
Brake Linkage				
Accumulators				
Parking Brake				
Hydraulic Pump				
Hydraulic Cooler				
Hydraulic Filter Condition				
Notes			•	
	Condition	Remarks	Parts	Labor
Leaks	Yes No NA			
		Remarks	Parts	Labor
Holding What Gear?				

TANDEMS

(Condi	ondition: N=New			ew	VG	=Very	Good G =Good F =Fair P =Poor NA =Not	Applicable	
		N	VG	G	F	Ρ	NA	Remarks	Parts	Labor
Tandems										
Wheel Lugs & Rims										
Differential										
Differential Lock	۲ [

HYDRAULICS

. .

Condition: N=New					VG	=Very	y Good G =Good F =Fair P =Poor NA =Not Ap	plicable	
	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Overall Operating Condition									
Tank									
Pumps & Valves									
Hose Lines									
Linkage									
Side Shift Cylinder									
Lift Cylinders									
Tip Cylinder									
Wheel Lean									

.

Cylinder				
Turn Drive Box		ose swivel or hoses leaking - dripping off pan.		
Circle, Shoes & Plates		CM and lift sockets have excessive slack.		
Circle A Frame				
Circle Side Shift Cylinder				
Scar. Lift Arms & Gear Box				
Ripper/Scar. Lift Cylinder				
Drive Line				
Filter Condition (CUT)				
Notes				
	Condition	Remarks	Parts	Labor
Leaks	Yes No NA			

BLADE

Con	ndition: N=New			ew	VG=Very Good			=Good	F =Fair	P =Poor	NA=Not Ap	plicable	
	N	VG	G	F	Р	NA			Remark	s		Parts	Labor
Face / Moldboard													
Cutting Edge Condition													
Circle													
A-Frame													
Notes													
							Rema	arks				Parts	Labor
Blade Size							14	4'					

RIPPER

Cor	nditio	on:	N=N	ew	VG	=Very	/ Good G =Good F =Fair P =Poor NA =Not Ap	NA=Not Applicable	
	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Pins & Bushings									
Brackets / Studs									
Beam / Frame									
Shanks / GET									
Lines / Fittings									

SCARIFER

. .

Co	onditio	on:	N=N	ew	VG=	=Very	Good	G =Good	F =Fair	P=Poor	NA=Not Ap	plicable
			1									

	N	VG	G	F	Ρ	NA	Remarks	Parts	Labor
Pins & Bushings									

Brackets / Studs		
Beam / Frame		
Shanks / GET		
Lines / Fittings		

SNOW WING

Con	Condition:			N=New V		VG=Very Good		G=Good	F =Fair	P=Poor	NA=Not Ap	plicable	
	N	VG	G	F	Р	NA			Remarl	s		Parts	Labor
Operating Condition													
Cylinder Condition													
Rear Post													
Moldboard													

TIRES

. .

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	I	Recappe	d	Tread Cuts/Chunks			Side Cuts Section	
Right Front	М		65	Yes	No 💽	NA	Yes	No ●		Yes	
Right Rear Center	М		65	Yes	No ●		Yes	No ●		Yes	
Right Rear	М		65	Yes	No	NA	Yes	No ●		Yes	
Left Front	М		65	Yes	No	NA	Yes	No		Yes	
Left Rear Center	М		65	Yes	No ●	NA	Yes	No ●		Yes	
Left Rear	М		65	Yes	No	NA	Yes	No ●		Yes	
Tire Size	17.5 R 25										
Average Life Remaining											
Notes	Notes										
		Condition				Rei	marks			Parts	Labor
Spare	Yes	No									
		Remarks								Parts	Labor
Number of Chains											
Chains Type (Cross Barr, Mesh)										
Percentage Remaining on Chains											

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

Remarks	Parts	Labor
Machine has EXT WRRTY through 12/18. Active service code #6 injector not responding. RH step bent a little.		
Needs windshield wiper blades. RH mirror cracked. Transmission return hose wet at clamp.		
Steering hoses not clamped down properly. Circle hose swivel or hoses leaking - dripping off pan. HYDO low.		

DCM and lift sockets have excessive slack. Couple moldboard wear strips fell out - missing.	