

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	SYS01986	3/6/2002		Terry Stephenson Breakdown	42	\$0.00	\$0.00	\$0.00
			finished installing radiator and pulled left front idler, also fixed oil leaks on engine					
				Totals for SYS01986		\$0.00	\$0.00	\$0.00
	SYS01999	3/6/2002		Troy Bentley Breakdown	42	\$0.00	\$0.00	\$0.00
			finished installing radiator					
				Totals for SYS01999		\$0.00	\$0.00	\$0.00
	SYS01968	3/5/2002		Troy Bentley Breakdown	42	\$0.00	\$0.00	\$0.00
			radiator installed					
				Totals for SYS01968		\$0.00	\$0.00	\$0.00
	SYS01979	3/5/2002		Bruce Thomas Breakdown	42	\$0.00	\$0.00	\$0.00
			helped with radiator problem					
				Totals for SYS01979		\$0.00	\$0.00	\$0.00
	SYS01950	3/4/2002		Troy Bentley Breakdown	42	\$0.00	\$0.00	\$0.00
			cut pins to get radiator out and took core down to radiator repair also replaced pulley for fan drive					
				Totals for SYS01950		\$0.00	\$0.00	\$0.00
	SYS01965	3/4/2002		Terry Stephenson Breakdown	42	\$0.00	\$0.00	\$0.00
			worked on repairing radiator					
				Totals for SYS01965		\$0.00	\$0.00	\$0.00
	SYS01941	3/2/2002		Troy Bentley Breakdown	42	\$0.00	\$0.00	\$0.00
			radiator repair					
				Totals for SYS01941		\$0.00	\$0.00	\$0.00
	SYS01925	3/1/2002		Troy Bentley Breakdown	42	\$0.00	\$0.00	\$0.00
			started to pull radiator					
				Totals for SYS01925		\$0.00	\$0.00	\$0.00
	SYS01911	2/28/2002		Troy Bentley Breakdown	42	\$0.00	\$0.00	\$0.00
			pulled radiator for repairs					
				Totals for SYS01911		\$0.00	\$0.00	\$0.00
	SYS01915	2/28/2002		Terry Stephenson Breakdown	42	\$0.00	\$0.00	\$0.00
			radiator repair					
				Totals for SYS01915		\$0.00	\$0.00	\$0.00
	SYS01677	2/8/2002	2,318 Hours	Bruce Thomas PM Services	PM	\$0.00	\$0.00	\$0.00
			A-PM					
				Totals for SYS01677		\$0.00	\$0.00	\$0.00
	SYS01557	1/26/2002	2,239 Hours	Terry Stephenson Breakdown	40	\$0.00	\$0.00	\$0.00
			replaced muffler					
				Totals for SYS01557		\$0.00	\$0.00	\$0.00
	SYS01566	1/25/2002		Terry Stephenson Breakdown	40	\$0.00	\$0.00	\$0.00
			checked muffler problem					
				Totals for SYS01566		\$0.00	\$0.00	\$0.00

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	SYS06160	9/6/2002		Terry Stephenson Breakdown	65	\$0.00	\$0.00	\$0.00
			checked hydraulic leaks					
				Totals for SYS06160		\$0.00	\$0.00	\$0.00
	SYS06026	8/27/2002		Terry Stephenson Breakdown	50	\$0.00	\$0.00	\$0.00
			changed cutting edge					
				Totals for SYS06026		\$0.00	\$0.00	\$0.00
	SYS06039	8/27/2002		Troy Bentley Breakdown	50	\$0.00	\$0.00	\$0.00
			replacd cutting edge					
				Totals for SYS06039		\$0.00	\$0.00	\$0.00
	SYS05809	8/12/2002	2,823 Hours	Bill Huber PM Services	PM	\$0.00	\$0.00	\$0.00
			A-PM					
				Totals for SYS05809		\$0.00	\$0.00	\$0.00
	SYS05911	8/9/2002		Troy Bentley Breakdown	43	\$0.00	\$0.00	\$0.00
			did muffler work					
				Totals for SYS05911		\$0.00	\$0.00	\$0.00
	SYS05777	8/6/2002		Terry Stephenson Breakdown	43	\$0.00	\$0.00	\$0.00
			repaired exhaust					
				Totals for SYS05777		\$0.00	\$0.00	\$0.00
	SYS05713	8/1/2002		Terry Stephenson Breakdown	43	\$0.00	\$0.00	\$0.00
			repair exhaust muffler					
				Totals for SYS05713		\$0.00	\$0.00	\$0.00
	SYS05697	7/31/2002		Troy Bentley Breakdown	30	\$0.00	\$0.00	\$0.00
			trouble shoot electrical on lights					
				Totals for SYS05697		\$0.00	\$0.00	\$0.00
	SYS05382	7/16/2002		Terry Stephenson Breakdown	13	\$0.00	\$0.00	\$0.00
			repaired brakes					
				Totals for SYS05382		\$0.00	\$0.00	\$0.00
	SYS05358	7/12/2002		Troy Bentley Breakdown	30	\$0.00	\$0.00	\$0.00
			troubleshoot low voltage in lights					
				Totals for SYS05358		\$0.00	\$0.00	\$0.00
	SYS04907	6/22/2002		Troy Bentley Breakdown	26	\$0.00	\$0.00	\$0.00
			replaced shift cable					
				Totals for SYS04907		\$0.00	\$0.00	\$0.00
	SYS04260	5/30/2002		Terry Stephenson Breakdown	26	\$0.00	\$0.00	\$0.00
			repaired transmission shifter					
				Totals for SYS04260		\$0.00	\$0.00	\$0.00
	SYS04073	5/22/2002		Troy Bentley Breakdown	20	\$0.00	\$0.00	\$0.00
			replaced track guide					
				Totals for SYS04073		\$0.00	\$0.00	\$0.00

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	SYS07060	11/6/2002		Danny Barney Breakdown	10	\$0.00	\$0.00	\$0.00
			welded on dozers					
				Totals for SYS07060		\$0.00	\$0.00	\$0.00
	SYS07068	11/6/2002		Troy Bentley Breakdown	02	\$0.00	\$0.00	\$0.00
			installed belly pans					
				Breakdown	30	\$0.00	\$0.00	\$0.00
			trouble shoot electrical and repaired lights					
				Totals for SYS07068		\$0.00	\$0.00	\$0.00
	SYS07042	11/4/2002		Danny Barney Breakdown	10	\$0.00	\$0.00	\$0.00
			welded on corner of dozer blade					
				Totals for SYS07042		\$0.00	\$0.00	\$0.00
	SYS07037	11/1/2002		Troy Bentley Breakdown	10	\$0.00	\$0.00	\$0.00
			worked on blade					
				Breakdown	30	\$0.00	\$0.00	\$0.00
			replaced master switch					
				Totals for SYS07037		\$0.00	\$0.00	\$0.00
	SYS07027	10/31/2002		Terry Stephenson Breakdown	10	\$0.00	\$0.00	\$0.00
			worked on dozer					
				Totals for SYS07027		\$0.00	\$0.00	\$0.00
	SYS06847	10/22/2002		Troy Bentley Breakdown	62	\$0.00	\$0.00	\$0.00
			bladed repair					
				Totals for SYS06847		\$0.00	\$0.00	\$0.00
	SYS06827	10/21/2002		Troy Bentley Breakdown	62	\$0.00	\$0.00	\$0.00
			blade repair					
				Totals for SYS06827		\$0.00	\$0.00	\$0.00
	SYS06803	10/18/2002		Troy Bentley Breakdown	30	\$0.00	\$0.00	\$0.00
			replaced starter					
				Breakdown	42	\$0.00	\$0.00	\$0.00
			radiator repair					
				Breakdown	60	\$0.00	\$0.00	\$0.00
			repaired ripper linkage					
				Totals for SYS06803		\$0.00	\$0.00	\$0.00
	SYS06804	10/18/2002		Terry Stephenson Breakdown	40	\$0.00	\$0.00	\$0.00
			worked on engine miss					
				Breakdown	42	\$0.00	\$0.00	\$0.00
			finished radiator					
				Breakdown	65	\$0.00	\$0.00	\$0.00
			worked on hydraulic valve					
				Totals for SYS06804		\$0.00	\$0.00	\$0.00
	SYS06794	10/17/2002		Troy Bentley Breakdown	42	\$0.00	\$0.00	\$0.00
			radiator repair					
				Breakdown	62	\$0.00	\$0.00	\$0.00
			welded on blade					
				Totals for SYS06794		\$0.00	\$0.00	\$0.00

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	S10978	11/5/2004	3,850 Hours Bellypan -PM	Anthony Dixon PM Services	PM	\$0.00	\$14.25	\$14.25
				Totals for S10978		\$0.00	\$14.25	\$14.25
	S10286	7/27/2004	install sprocket segments	Robert Hansen Routine Work	22	\$0.00	\$108.00	\$108.00
				Totals for S10286		\$0.00	\$108.00	\$108.00
	S10544	7/19/2004	3,614 Hours Adj. linkage Adj. psi for hyd. pump	Terry Stephenson Routine Work Routine Work	15 65	\$0.00 \$0.00	\$165.00 \$0.00	\$165.00 \$0.00
				Totals for S10544		\$0.00	\$165.00	\$165.00
	S10239	6/30/2004	3,606 Hours A-PM.	Anthony Dixon PM Services	PM	\$0.00	\$14.25	\$14.25
				Totals for S10239		\$0.00	\$14.25	\$14.25
	S10499	6/22/2004	3,603 Hours Repair wiring harness for water flow alarm Repair guards for radiator, clean	Terry Stephenson Routine Work Routine Work	30 42	\$0.00 \$0.00	\$0.00 \$495.00	\$0.00 \$495.00
				Totals for S10499		\$0.00	\$495.00	\$495.00
	S10576	6/22/2004	3,603 Hours Remove nose & side panels for cleaning, repair, instal new seat	Robert Hansen Routine Work	02	\$0.00	\$216.00	\$216.00
				Totals for S10576		\$0.00	\$216.00	\$216.00
	S10133	6/10/2004	Help terry.	Robert Hansen Routine Work	MS	\$0.00	\$36.00	\$36.00
				Totals for S10133		\$0.00	\$36.00	\$36.00
	S10134	6/10/2004	Service a/c Replace #2 injector line and install line clamp.	Terry Stephenson Routine Work	MS	\$0.00	\$110.00	\$110.00
				Totals for S10134		\$0.00	\$110.00	\$110.00
	S09997	4/23/2004	3,463 Hours replace water pump and rad. hoses. Repair broken alt. and oil cooler brackets. Clean belly pan.	Terry Stephenson Routine Work	MS	\$0.00	\$440.00	\$440.00
				Totals for S09997		\$0.00	\$440.00	\$440.00
	S09998	4/22/2004	Helped Terry.	Robert Hansen Routine Work	MS	\$0.00	\$360.00	\$360.00
				Totals for S09998		\$0.00	\$360.00	\$360.00
	S09803	3/11/2004	3,404 Hours A-PM., B-PM., C-PM.	Anthony Dixon PM Services	PM	\$0.00	\$114.00	\$114.00
				Totals for S09803		\$0.00	\$114.00	\$114.00
	S09205	10/6/2003	3,329 Hours A PM	Anthony Dixon PM Services	PM	\$0.00	\$28.50	\$28.50
				Totals for S09205		\$0.00	\$28.50	\$28.50

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	S19211	2/25/2010		Steven Price Routine Work	02	\$0.00	\$180.00	\$180.00
			repair blade					
				Totals for S19211		\$0.00	\$180.00	\$180.00
	S19200	2/17/2010		Steve Gutierrez Routine Work	90	\$0.00	\$756.00	\$756.00
			weld and repair blade frog (replace LH frog)					
				Totals for S19200		\$0.00	\$756.00	\$756.00
	S19172	11/9/2009	6,691 Hours	Anthony Dixon PM Services	PM	\$0.00	\$0.00	\$0.00
			PM					
				Totals for S19172		\$0.00	\$0.00	\$0.00
	S19173	11/9/2009	6,691 Hours	Anthony Dixon PM Services	PM	\$0.00	\$0.00	\$0.00
				Totals for S19173		\$0.00	\$0.00	\$0.00
	S18909	11/4/2009		Troy Bentley Routine Work	50	\$0.00	\$165.00	\$165.00
			Pull belly pan. Repair cab filter. housing drain tranny oil					
				Totals for S18909		\$0.00	\$165.00	\$165.00
	S18092	12/6/2008	6,467 Hours	Anthony Dixon PM Services	PM	\$0.00	\$14.25	\$14.25
			A-PM DONE					
				Totals for S18092		\$0.00	\$14.25	\$14.25
	S17986	11/15/2008	6,424 Hours	Terry Stephenson Routine Work	26	\$0.00	\$330.00	\$330.00
			RESEAL BEARING TONGUE CONVERTER REPLACE TRANS PUMP					
				Totals for S17986		\$0.00	\$330.00	\$330.00
	S17703	10/2/2008	6,295 Hours	Terry Stephenson Routine Work	01	\$0.00	\$220.00	\$220.00
			REPLACE CONDENSER FOR A.C. AND RECHARGE SYSTEM					
				Totals for S17703		\$0.00	\$220.00	\$220.00
	S17408	6/26/2008	6,070 Hours	Anthony Dixon PM Services	PM	\$0.00	\$85.50	\$85.50
			A-PM DONE B-PM DONE C-PM DONE					
				Totals for S17408		\$0.00	\$85.50	\$85.50
	S17409	6/26/2008	6,070 Hours	PM Services	PM	\$0.00	\$28.50	\$28.50
			BELLY PAN - DONE					
				Totals for S17409		\$0.00	\$28.50	\$28.50
	S16717	1/30/2008	5,917 Hours	Troy Bentley Routine Work	40	\$0.00	\$71.50	\$71.50
			REPAIRED MISC. CRACK & ETC AS ASSEMBLY REQUIRED					
				Totals for S16717		\$0.00	\$71.50	\$71.50
	S16050	1/29/2007		Troy Bentley Routine Work	02	\$0.00	\$220.00	\$220.00
			REPAIR DOOR HINGE					
				Totals for S16050		\$0.00	\$220.00	\$220.00

Unit Report

Repair Order History

Unit Number (Category) Vendor (Invoice)	RO Number	Date	Meter Reading Work Description	Mechanic / Vendor Repair Reason	Code	Parts Amount	Labor Amount	Total Amount
	S22185	4/12/2012	7,814 Hours	Terry Stephenson				
				Routine Work	01	\$0.00	\$462.00	\$462.00
			replace ac condenser and receiver dryer	Routine Work	21	\$0.00	\$203.00	\$203.00
			recharge a/c	Routine Work	42	\$0.00	\$14.50	\$14.50
			pull radiator cores (8(and send to Cat for repairs install radiator cores repair fan fan shroud fill with new antifreeze					
				Totals for S22185		\$0.00	\$679.50	\$679.50
	S21780	12/7/2011	7,610 Hours	Terry Stephenson				
				Routine Work	40	\$0.00	\$275.00	\$275.00
			reseal oil cooler for engine and related air and water lines repair radiator neck for leaky cap					
				Totals for S21780		\$0.00	\$275.00	\$275.00
	S21328	8/9/2011		Terry Stephenson				
				Routine Work	40	\$0.00	\$1,116.50	\$1,116.50
			repalce wter pump, temp regulator and flow switch at Summer Horse Canyon					
				Totals for S21328		\$0.00	\$1,116.50	\$1,116.50
	S20972	5/3/2011		Terry Stephenson				
				Routine Work	65	\$0.00	\$110.00	\$110.00
			repair o ring on ripper control valve					
				Totals for S20972		\$0.00	\$110.00	\$110.00
	S20973	5/3/2011		Terry Stephenson				
				Routine Work	30	\$0.00	\$110.00	\$110.00
			repair wire harness under floor					
				Totals for S20973		\$0.00	\$110.00	\$110.00
	S20940	4/27/2011	7,154 Hours	Kyle Bundy				
				Routine Work	40	\$0.00	\$43.50	\$43.50
			repair fuel leak on pump					
				Totals for S20940		\$0.00	\$43.50	\$43.50
	S20260	11/17/2010	6,870 Hours	Terry Stephenson				
				Routine Work	90	\$0.00	\$330.00	\$330.00
			replace cutting edge and corner bits					
				Totals for S20260		\$0.00	\$330.00	\$330.00
	S20246	11/15/2010		Terry Stephenson				
				Routine Work	90	\$0.00	\$165.00	\$165.00
			change broken corner bit L Hisich					
				Totals for S20246		\$0.00	\$165.00	\$165.00
	S19985	9/20/2010	6,811 Hours	Kyle Bundy				
				Routine Work	40	\$0.00	\$0.00	\$0.00
			tighten alt and a/c belts					
				Totals for S19985		\$0.00	\$0.00	\$0.00
	S19458	5/18/2010	6,737 Hours	Terry Stephenson				
				Routine Work	01	\$0.00	\$110.00	\$110.00
			service AC					
				Totals for S19458		\$0.00	\$110.00	\$110.00
	S19289	3/18/2010	6,729 Hours	Kyle Bundy				
				Routine Work	16	\$0.00	\$3,080.00	\$3,080.00
			new pins, bushings and rods in equalizer bar					
				Totals for S19289		\$0.00	\$3,080.00	\$3,080.00

Labor Costs are not reported for Secured Employees

WO#	Equipment	WO Date Trx Date	Status Source	Service/Expense Code Vendor/Emp/Whse	Description	Qty	UM	Unit Cost	Extended Cost																																																																																
2570	DD8N8 - D8N	11/01/17	Closed	100 -Routine Maintenance		.00		.00	335.01																																																																																
		11/01/17	A/P	Wheeler Machinery																																																																																					
<table border="0" style="width: 100%;"> <tr> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> </tr> <tr> <td colspan="6"></td> <td style="text-align: right;">WO 2570</td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Labor Total</td> <td style="text-align: right;">.00</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Other Total</td> <td style="text-align: right;">335.01</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Total</td> <td style="text-align: right;">335.01</td> </tr> </table>																										WO 2570												Labor Total	.00									Other Total	335.01									Total	335.01																														
						WO 2570																																																																																			
								Labor Total	.00																																																																																
								Other Total	335.01																																																																																
								Total	335.01																																																																																
2985	DD8N8 - D8N	01/01/18	Closed	100 -Routine Maintenance		.00		.00	21.13																																																																																
		01/01/18	A/P	Castle Country Hydraulic & Sup																																																																																					
<table border="0" style="width: 100%;"> <tr> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> </tr> <tr> <td colspan="6"></td> <td style="text-align: right;">WO 2985</td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Labor Total</td> <td style="text-align: right;">.00</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Other Total</td> <td style="text-align: right;">21.13</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Total</td> <td style="text-align: right;">21.13</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Labor Grand Total</td> <td style="text-align: right;">.00</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Other Grand Total</td> <td style="text-align: right;">3,190.62</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Grand Total</td> <td style="text-align: right;">3,190.62</td> </tr> </table>																										WO 2985												Labor Total	.00									Other Total	21.13									Total	21.13									Labor Grand Total	.00									Other Grand Total	3,190.62									Grand Total	3,190.62
						WO 2985																																																																																			
								Labor Total	.00																																																																																
								Other Total	21.13																																																																																
								Total	21.13																																																																																
								Labor Grand Total	.00																																																																																
								Other Grand Total	3,190.62																																																																																
								Grand Total	3,190.62																																																																																